Technician: ***CHANTELLE*** Date: ***JUNE 14 2023***

Customer Name: ***PATTON MOTORCARS***

Yr./Make/Model: ***2006 BMW 325I***

VIN: **WBAVB13546KR64303**

Mileage: **225,685** Repair Order #: **1236**

BRAKE AND TIRE

Left Front	Right Front
Brake Lining 9 mm	Brake Lining 9 mm
Tire Tread 9 32nds	Tire Tread 7 32nds
Wear Pattern EVEN	Wear Pattern EVEN
Tire Pressure PSI	Tire Pressure PSI
Before ____ After 32	Before ____ After 32
Rotor / Drum	Rotor / Drum

Alignment Check Needed

Wheel Balance Needed

Left Rear	Right Rear
Brake Lining 8 mm	Brake Lining 8 mm
Tire Tread 8 32nds	Tire Tread 8 32nds
Wear Pattern EVEN	Wear Pattern EVEN
Tire Pressure PSI	Tire Pressure PSI
Before ____ After 39	Before ____ After 39
Rotor / Drum	Rotor / Drum

Brake Inspection Not Performed This Visit

PRIOR BODY DAMAGE



X ADVISOR

X CUSTOMER ACKNOWLEDGMENT

COMMENTS / ESTIMATES

FRESH SERVICE-FLUID TOP UPS - RECENT OIL CHANGE

AC BLOWS COLD
GOOD TOYO TIRES FRONT AND REAR

GOOD BRAKES FRONT AND REAR
NEWER OIL PAN GASKET

GOOD BATTERY
NEXT SERVICE DUE @ 233,649

CHECKED AND OKAY
MAY NEED FUTURE ATTENTION
REQUIRES IMMEDIATE ATTENTION

INTERIOR / EXTERIOR

✔			Head Lights / Tail Lights / Turn Signals / Brake Lights / Hazard Warning Lights / Exterior Lamps / License Plate Lights
✔			Windshield Washer Spray / Wiper Operation / Wiper Blades
✔			Windshield Condition (Inspect for Cracks, Chips, or Pitting)
✔			Mirrors / Glass
✔			Emergency Brake Adjustment
✔			Horn Operation
✔			Fuel Tank Cap Gasket
✔			Air Conditioning Filter (if equipped)
			Clutch Operation (if equipped)
✔			Back-up Lights Left / Right
✔			Dash Warning Lights
✔			Carpet / Upholstery / Floor Mats

UNDER VEHICLE

✔			Shock Absorbers / Suspension / Struts
✔			Steering Gear Box / Linkage and Boots / Ball Joints / Dust Covers
✔			Muffler / Exhaust Pipes / Mountings / Catalytic Converter
	✔		Engine Oil and/or Fluid Leaks
✔			Brake Lines / Hoses / Parking Brake Cable
✔			Drive Shaft Boots / Constant Velocity Boots / U-joints / Transmission Linkage (if equipped)
✔			Transmission / Differential / Transfer Case (Check Fluid Level, Fluid Condition and Fluid Leaks)
✔			Fuel Lines and Connections / Fuel Tank Band / Fuel Tank Vapor Vent Systems Hoses
✔			Inspect Nuts and Bolts on Body Chassis

UNDER HOOD

✔			Fluid Levels: Oil / Coolant / Battery / Power Steering / Brake Fluid / Washer / Automatic Transmission
	✔		Engine Air Filter
✔			Drive Belts (condition and adjustment)
✔			Cooling System Hoses / Heater Hoses / Air Conditioning Hoses and Connections
✔			Radiator Core / Air Conditioning Condenser (if equipped)
✔			Coolant Recovery Reservoir Fluid Level / Condition
✔			Clutch Reservoir Fluid / Condition (as equipped)

INTERIOR/EXTERIOR

✔			Battery Terminal / Cables / Mountings
✔			Check Condition of Battery (Storage Capacity Test)

✔ Pass Recharge Retest Fail

Factory Spec Cold Cranking Amps 720

Actual Cold Cranking Amps 680