Technician: ***CHANTELLE*** Date: ***JULY 4 2023***

Customer Name: ***PATTON MOTORCARS***

Yr./Make/Model: ***2006 BMW 330I***

VIN: **WBAVB33516KR77490**

Mileage: **264,242** Repair Order #: **1255**

## BRAKE AND TIRE

**Left Front**

- ✔ Brake Lining 9 mm
- ✔ Tire Tread 7 32nds
- ✔ Wear Pattern CAMBER
- Tire Pressure PSI
- Before 25 After 35

**Right Front**

- ✔ Brake Lining 9 mm
- ✔ Tire Tread 7 32nds
- ✔ Wear Pattern CAMBER
- Tire Pressure PSI
- Before 27 After 35

✔ Rotor / Drum

✔ Rotor / Drum

Alignment Check Needed

Wheel Balance Needed

**Left Rear**

- ✔ Brake Lining 8 mm
- ✔ Tire Tread 9 32nds
- ✔ Wear Pattern EVEN
- Tire Pressure PSI
- Before 34 After 38

**Right Rear**

- ✔ Brake Lining 8 mm
- ✔ Tire Tread 9 32nds
- ✔ Wear Pattern EVEN
- Tire Pressure PSI
- Before 33 After 38

✔ Rotor / Drum

✔ Rotor / Drum

**Brake Inspection Not Performed This Visit**

## PRIOR BODY DAMAGE



X ADVISOR

X CUSTOMER ACKNOWLEDGMENT

## COMMENTS / ESTIMATES

FREASH SERVICE-OIL CHANGE FLUID TOP UP

NEW OIL LEVEL SENSOR ORING
NEWER VALVE COVER GASKET

NEWER UPPER RADIATOR HOSE
GOOD TIRES FRONT AND REAR

GOOD BRAKES FRONT AND REAR
BATTERY TESTED GOOD UNDER LOAD TEST

**CHECKED AND OKAY**
**MAY NEED FUTURE ATTENTION**
**REQUIRES IMMEDIATE ATTENTION**

## INTERIOR / EXTERIOR

| | | | |
|---|---|---|---|
| ✔ | | | Head Lights / Tail Lights / Turn Signals / Brake Lights / Hazard Warning Lights / Exterior Lamps / License Plate Lights |
| ✔ | | | Windshield Washer Spray / Wiper Operation / Wiper Blades |
| ✔ | | | Windshield Condition (Inspect for Cracks, Chips, or Pitting) |
| ✔ | | | Mirrors / Glass |
| ✔ | | | Emergency Brake Adjustment |
| ✔ | | | Horn Operation |
| ✔ | | | Fuel Tank Cap Gasket |
| ✔ | | | Air Conditioning Filter (if equipped) |
| | | | Clutch Operation (if equipped) |
| ✔ | | | Back-up Lights Left / Right |
| ✔ | | | Dash Warning Lights |
| ✔ | | | Carpet / Upholstery / Floor Mats |

## UNDER VEHICLE

| | | | |
|---|---|---|---|
| ✔ | | | Shock Absorbers / Suspension / Struts |
| ✔ | | | Steering Gear Box / Linkage and Boots / Ball Joints / Dust Covers |
| ✔ | | | Muffler / Exhaust Pipes / Mountings / Catalytic Converter |
| ✔ | | | Engine Oil and/or Fluid Leaks |
| ✔ | | | Brake Lines / Hoses / Parking Brake Cable |
| ✔ | | | Drive Shaft Boots / Constant Velocity Boots / U-joints / Transmission Linkage (if equipped) |
| ✔ | | | Transmission / Differential / Transfer Case (Check Fluid Level, Fluid Condition and Fluid Leaks) |
| ✔ | | | Fuel Lines and Connections / Fuel Tank Band / Fuel Tank Vapor Vent Systems Hoses |
| ✔ | | | Inspect Nuts and Bolts on Body Chassis |

## UNDER HOOD

| | | | |
|---|---|---|---|
| ✔ | | | Fluid Levels: Oil / Coolant / Battery / Power Steering / Brake Fluid / Washer / Automatic Transmission |
| | ✔ | | Engine Air Filter |
| ✔ | | | Drive Belts (condition and adjustment) |
| ✔ | | | Cooling System Hoses / Heater Hoses / Air Conditioning Hoses and Connections |
| ✔ | | | Radiator Core / Air Conditioning Condenser (if equipped) |
| ✔ | | | Coolant Recovery Reservoir Fluid Level / Condition |
| | | | Clutch Reservoir Fluid / Condition (as equipped) |

## INTERIOR/EXTERIOR

| | | | |
|---|---|---|---|
| ✔ | | | Battery Terminal / Cables / Mountings |
| ✔ | | | Check Condition of Battery (Storage Capacity Test) |

✔ Pass  Recharge Retest  Fail

Factory Spec Cold Cranking Amps 710

Actual Cold Cranking Amps 665